

Chapter 4. Installation and connection

1. Shape and cutout hole dimension

Shape	Panel dimension W	Panel dimension H	Case dimension W	Case dimension H	Cutout hole dimension W	(unit: mm)
120×120square	120	120	110	110	80	112
96×96square	96	96	90	90	80	92
80×80square	80	80	74	74	80	76
72×72square	72	72	66	66	80	68
48×48square	48	48	44	44	70	45

2. Method of installation


Choose the corresponding hole cutout dimension from the table above, make a hole in the installation screen, insert the instruments into the hole, place the two clamping pieces into the clamping holder and push and tighten them by hand.

3. Terminal arrangement and function declaration of instrument (please accord to the one of instrument case)

3.1 Auxiliary power supply (POWER): The voltage range of operation is AC 220V/50/60Hz. It is suggested to install a fuse of 1A beside of the live wire when using the AC power supply to prevent damaging the instrument. In the areas with poor power quality, the surge suppressor and quick pulse group suppressor should be installed in the power supply circuit.

Electrical quantity signal input (I input): H represents " + " port of DC input signal, live wire terminal of AC voltage input signal and inlet wire terminal of AC current input signal. Input voltage should not be higher than the maximum value (AC 600V, or you should consider of using PT and installing fuse of 1A on voltage input port. While the current is higher than AC 10A, you should consider of using CT).

3.2 Typical connection



Chapter 5. Cautions

1. Please confirm if the power supply, input signal and each terminal wiring of the meter are correct and reliable before applying the power.

2. The instrument must be preheated for 15 minutes to guarantee the precision of measurement.

3. The instrument should not be tapped, knocked and vibrate excessively and its using environment should meet the technical requirements.

4. The meter has been calibrated according to the measuring range required by the customer upon order. The user should check once again if the measuring range of the meter is fit with the specifications of the transformer and set the measuring range again if not.

Chapter 6. Packing and Storage

The instrument and accessories with packing should keep storage conditions cool and dry and free of wet and corrosive gas with temperature not more than 70°C and not less than -40°C, and relative humidity≤85%RH.

Appendix 1: Example of programming

Example 1: The factory default parameter is AC 5A(CT=1), 0~600V(PT=1); If the voltage transformer is 10KV/100V should modify the CT multiplying power as 20(100/5), modify PT multiplying power as 100(10000/100)

Return upon error password



Press 2s

Return upon error password

Use □ □ □ to modify parameter

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

20(10000/100)

Return upon error password

Display

Press 2s

Applying power

Press 2s

Parameter

U U U U

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

U U U U

P L

